

NORTHWAY AIRPORT

Contents:

- A Pavement Strength Form showing project history, latest Pavement Condition Index (PCI) data, pavement strength ratings (if available) and other useful information
- A Pavement Condition Survey – PCI Sample Unit Layout Plan
- PCI maps showing as-measured and predicted pavement conditions
- Age map showing pavement age as of January 2003
- A Branch PCI Condition Report
- A Section PCI Condition Report

Airport Information:

- Location:
The Northway Airport is located along Northway Road, approximately 7 miles south of the Alaska Highway, Milepost 1263.
- District: South Central District, Northern Region
- Airport Manager: Jim Fehrenbacher
- District Maintenance Manager: George Lavasseur
- Pavement Surface: Asphalt Concrete
- Last Pavement Construction: 1993
- Pavement layout: The Runway is designated as 04-22 with asphalt concrete pavement measuring 5100' x 100'. It has an attached Taxiway/Apron that is 710' x 400'.
- Design Aircraft: General Aircraft
- 2001 Enplanements: 39
- Airport Class: Non-Primary
- Last pavement condition survey: 2002
- Next planned pavement condition survey: 2004
- 2002 reported pavement maintenance and/or changed conditions: Crack sealing with backer rod in summer. Severe earthquake damage in November of 2002 making airport unusable, reconstruction is underway.
- Recommendations: See PCI maps